

15/04/2025

HARDINGTON MANDEVILLE HIGHWAYS REPORT - APRIL 2025

Submitted	SC Ref.	Status	Status Date	Location	Brief Description	What Three Words
09/12/2024	828262	Rejected	09/12/2024	Lyatts Hill, outside Brookfield.	High ridge and subsidence either side.	pouch.parading.package
10/12/2024	829895	Complete	Future	Pig Hill, Rose Cottage	Sunken drain. Significant risk to vehicle suspensions.	cobble.glance.found
10/12/2024	829904	Complete	Future	Lyatts Lane, 30m from Primrose Hill	Badly subsided carriageway with centre ridge.	partner.memo.nourished
10/12/2024	829906	Complete	Future	North Lane, outside Peach Tree Cott.	Pothole.	syndicate.buzz.glare
10/12/2024	829908	Complete	Future	North Lane, opp new cottage.	Major subsidence of carriageway with center ridge.	tens.fired.parked
10/12/2024	829909	Complete	Future	North Lane, opp new cottage.	Major subsidence of carriageway with center ridge.	condensed.animal.hangs
10/12/2024	829911	Complete	Future	North Lane, opp Milcombe Farm.	Several potholes, surface broken.	sagging.sparrows.grouping
29/01/2025	835581	Complete	Future	Pig Hill by Hill Springs	Two drains blocked and overflowing. Need jetting.	blues.clasping.vowed
03/02/2025	836601	Issued	16/02/2025	Penn Lane/Barry Lane Junction	Pothole.	passively.snores.visual
18/03/2025	841592	Review	18/03/2025	High Street/Broadstone Lane	Tarmac eroded around services covers.	argue.shred.ticked

Summary: Logged 10, Rejected 1, Future 7, Review 1, Issued 1